

Figure 1




Figure 2a

Shear stresses at point B

Stresses (daN/mm²)




Figure 2b

Shear stresses at point A




Figure 3a

Shear stresses at point B




Figure 3b

Shear stresses at point A

Figure 4a

Shear stresses at point B

Stresses (daN/mm²)

0.1
0.08
0.04
0.02
0.02
0.04
0.06
0.08
0.08
0.08
0.08
Azimuth (Deg)

Figure 4b




Figure 5

Shear stresses at point A




Figure 6a

Shear stresses at point B




Figure 6b




Figure 7






Figure 8








Figure 10




Figure 11

P10-1380




Figure 12

Shear stress (daN/mm2)

Outside the stress of the stress o




Figure 13

Principle of thresholding the differentiated signal




Figure 14




Figure 15




Figure 16




Figure 17